




PASSO 1




PASSO 2




PASSO 3




PASSO 4





PASSO 5




PASSO 6



PASSO 7

PASSO 8

PASSO 9

1


x5

2


x1

3


x1

4


x1

5



x1

6



x1

7



x1

8


x1


9


x1

A


M6x20mm

x6


B


x1

C



M6xΦ16x1.5mm

x4

D


M6x30mm

x4

E


M6x25mm

x2