




PASSO 1




PASSO 2




PASSO 3




PASSO 4




PASSO 5




PASSO 6




PASSO 7




PASSO 8



PASSO 9




1




x5

2



x1

3




x1

4



x1

5



x1

6




x1

7




x1

8




x1

9



x1

10



x1


A



M6x30mm

x6

B



x1

C



M8x35mm

x3

D



M6x Φ 16x1.5mm

x4

E



M6x25mm

x4